

Corrections for the 1933-1934 Ford Book - authored by Cliff Helling

Corrections for the 1933-34 Ford Book . authored by Cliff Helling

- Chapter 3 page 21:** picture of starter – add to caption: see Chapter 1 page 7 for early starter (1932 -36) endplate.
- Chapter 3 page 22:** middle picture caption should be anti-squeak part number 40-4562
- Chapter 6 page 20:** Paragraph 2 – replace sentence “The 1934 receptacle diameter is 7/16” while the 1933 receptacle is 13/32” with “The 1934 receptacle diameter is 15/16” while the 1933 receptacle diameter is 27/32”.
- Chapter 7 page 14:** lower right picture caption – change O to R and add – correct patent plate picture is middle left on page 16.
- Section D page 17:** middle picture should say Model 46-830.

April 2008
END